


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

| Test ID | Test Type | Date Inspected | Company / Super. | Blower MH | Ground Condition | Notification Made? | Total Length |
|-----------|-----------|----------------|------------------|-------------|------------------|--------------------|--------------|
| S1028-223 | Smoke | 8/10/2009 | ADS/TM | S19MM_009MH | Dry | Yes | 451.81 |



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

| Test ID | Test Type | Date Inspected | Company / Super. | Blower MH | Ground Condition | Notification Made? | Total Length |
|-----------|-----------|----------------|------------------|-------------|------------------|--------------------|--------------|
| S1028-223 | Smoke | 8/10/2009 | ADS/TM | S19MM_009MH | Dry | Yes | 451.81 |

Isolated Pipes

| Pipe ID | Upstream MH | Downstream MH | Length (ft) | Diameter (In) |
|-------------|-------------|---------------|-------------|---------------|
| S19MM_023G1 | S19MM_023DE | S19MM_017MH | 114.772 | 8 |
| S19MM_009G1 | S19MM_009MH | S19MM_017MH | 231.294 | 8 |
| S19KK_005G1 | S19KK_005MH | S19MM_009MH | 90.5567 | 8 |
| S19MM_017G1 | S19MM_017MH | S19MM_013MH | 15.1849 | 8 |

Observations & Photos

